



**ORNL**

NEUTRON SCIENCES



**Branson/VWR Sonic Bath  
Models: 1510, 2510, 3510,  
5510, and 8510**



9

Lid



8

Water  
Containment  
Area



Status Indication



6

LED Display

7

1

Power Switch

2

On/Off and mode  
switch

3

Set Display


4

Clear Display


5

Select Option

# SETUP



# OPERATION



# HAZARDS



## ELECTRICAL HAZARD

This equipment contains liquid near electrical connections.



## HEAT HAZARD

This equipment heats liquids and may cause burns.



## PINCH HAZARD

This equipment contains moving parts near the lid/agitator that may cause physical harm.



## VAPOR HAZARD

Because cleaning agents and chemicals are used in this unit, please be aware of of vapor hazards and use a fume hood if needed.



## Fire Hazard

Improper use of this unit including the use of incompatible fluids can cause a fire hazard.

# PREVENTION



## EYE PROTECTION

Wear safety glasses while operating.



## PROTECTIVE GLOVES

Wear appropriate gloves for heat and chemical usage.



## NON-SLIP, CLOSED SHOES

Wear non-slip, closed shoes to avoid spills.



## READ MANUAL

Become familiar with this guide before operating.

For additional help contact the Lab  
Space Manager